




KM2000-1 part list

P/N	Description	Quantity
1	Motor End Cover	1
2	Motor Assembly	1
3	Gearbox Housing	1
4	Planetary Gear Assembly	1
5	Ring Gear	1
6	Cover plate	1
7	Screw M4*10	4
8	Sliding Bearing	1
9	Drive Shaft	1
10	Pin $\phi 2.5 \times 12$	1
11	Spline	1
12	Spring	1
13	Drum	1
14	Screw M5*8	1

P/N	Description	Quantity
15	Support Ring	1
16	Flange Nut M5	1
17	Tension Plate	1
18	Frame Assembly	1
19	Knob	1
20	Screw M5*10	2
21	Screw M6*16	2
22	Wire Rope	1
23	Hook	1
24	Hand Saver Strap	1
25	Switch Assembly	1
26	Circuit Breaker	1
27	Triangulation Holder	1