

KX95122H-1 part list

P/N	Description	Quantity
1	Screw M5*20	8
2	Spring Washer φ5	8
3	Gearbox End Cover	1
4	Screw M6*10	1
5	Clutch Handle Pin	1
6	Clutch Handle Spring	1
7	Clutch Handle Sheath	1
8	Clutch Handle	1
9	Clutch Handle Screw M4*16	1
10	O-Ring φ10	1
11	Bearing	1
12	Sun Gear	1
13	Ring Gear	1
14	Retainer Ring	1
15	1st Planetary Gear Assembly	1
16	2nd Planetary Gear Assembly	1
17	Washer	1
18	3rd Planetary Gear Assembly	1
19	Power Cord	1
20	Socket Cover	1
21	Control Box Cover	1
22	Socket	1
23	Solenoid	1
24	Sheath	4
25	Screw M5*16	4
26	Control Box Top Cover	1
27	Control Box Base Cover	1
28	Tie bar	1
29	Wireless Remote receiver	1
30	Flat Washer φ8	4
31	Screw M8*30	4

P/N	Description	Quantity
32	Motor Assembly	1
33	Motor Base	1
34	Brake Assembly	1
35	Drive Shaft	1
36	Wire Rope	1
37	Drum	1
38	Screw M5*16	8
39	Spring Washer φ5	8
40	Gasket Ring	2
41	Sliding Bearing	2
42	Gearbox Cover	1
43	O-Ring φ122	1
44	Gearbox Housing	1
45	O-Ring φ122	1
46	Ring Gear	1
47	Screw M12*25	2
48	Flat Washer φ12	2
49	Spring Washer φ12	2
50	Nut M12	2
51	Roller Fairlead	1
52	Handle Switch Assembly	1
53	Hook	1
54	Hand Saver Strap	1
55	Circuit Breaker	3
56	Circuit Breaker Connection Plate	2
57	Wireless Remote	2
58	Nut M10	4
59	Flat Washer φ10	4
60	Spring Washer φ10	4
61	Screw M10*30	4

