




KX95122B-1 part list

P/N	Description	Quantity
1	Screw M4*16	10
2	Spring Washer ϕ 4	10
3	Gearbox End Cover	1
4	Seal	2
5	Bearing	1
6	Sun Gear	1
7	1st Planetary Gear Assembly	1
8	Ring Gear	1
9	2nd Planetary Gear Assembly	1
10	Washer	1
11	Ring Gear	1
12	Retainer Ring	1
13	3rd Planetary Gear Assembly	1
14	Gearbox Housing	1
15	O-Ring ϕ 11	1
16	Clutch Handle Spring	1
17	Clutch Handle Base	1
18	Clutch Handle	1
19	Clutch Handle Screw M4*16	1
20	Clutch Handle Pin	1
21	Screw M6*40	4
22	Control Box Right Cover	1
23	Gearbox Cover	1
24	Spring Washer ϕ 4	10
25	Screw M4*16	10
26	Drum	1
27	Gasket Ring	2
28	Sliding Bearing	2
29	Brake Assembly	1
30	Motor Base	1
31	Screw M3*12	2
32	Socket Cover	1
33	Socket	1

P/N	Description	Quantity
34	Screw M5*10	2
35	Control Box Base Cover	1
36	Solenoid	1
37	Control Box Top Cover	1
38	Sheath	1
39	Screw M4*10	3
40	Motor Cover	1
41	Drive Shaft	1
42	Screw M4*6	6
43	Screw M8*22	4
44	Control Box Left Cover	1
45	Sheath	1
46	Nut M8	4
47	Motor Assembly	1
48	Wire Rope	1
49	Hook	1
50	Hand Saver Strap	1
51	Screw M12*25	2
52	Roller Fairlead	1
53	Flat Washer ϕ 12	2
54	Spring Washer ϕ 12	2
55	Nut M12	2
56	Wireless Remote	2
57	Handle Switch Assembly	1
58	Power Cord	1
59	Circuit Breaker	3
60	Circuit Breaker Connection Plate	2
61	Power Cord	1
62	Wireless Remote receiver	1
63	Nut M10	4
64	Flat Washer ϕ 10	4
65	Spring Washer ϕ 10	4
66	Screw M10*30	4

