




KX95132-1 part list

P/N	Description	Quantity
1	Screw M5*20	8
2	Spring Washer $\phi 5$	8
3	Gearbox End Cover	1
4	Pin $\phi 3$	2
5	Screw M6*10	1
6	Clutch Handle Pin	1
7	Clutch Handle Spring	1
8	Clutch Handle Sheath	1
9	Clutch Handle	1
10	Clutch Handle Screw M4*16	1
11	O-Ring $\phi 10$	1
12	Bearing	1
13	Sun Gear	1
14	Small Ring Gear	1
15	Retainer Ring(small)	1
16	Ring Gear	1
17	Retainer Ring(big)	1
18	1st Planetary Gear Assembly	1
19	2nd Planetary Gear Assembly	1
20	Washer	1
21	3rd Planetary Gear Assembly	1
22	Power Cord	1
23	Socket Cover	1
24	Control Box Cover	1
25	Socket	1
26	Solenoid	1
27	Sheath	4
28	Screw M5*16	4
29	Control Box Top Cover	1
30	Control Box Base Cover	1
31	Tie bar	1
32	Wireless Remote receiver	1

P/N	Description	Quantity
33	Flat Washer $\phi 8$	4
34	Screw M8*30	4
35	Motor Assembly	1
36	Motor Base	1
37	Brake Assembly	1
38	Drive Shaft	1
39	Synthetic Rope	1
40	Drum	1
41	Screw M5*16	8
42	Spring Washer $\phi 5$	8
43	Gasket Ring	2
44	Sliding Bearing	2
45	Gearbox Cover	1
46	O-Ring $\phi 122$	1
47	Gearbox Housing	1
48	O-Ring $\phi 122$	1
49	Ring Gear	1
50	Screw M12*25	2
51	Aluminum Hawse Fairlead	1
52	Flat Washer $\phi 12$	2
53	Spring Washer $\phi 12$	2
54	Nut M12	2
55	Handle Switch Assembly	1
56	Hook	1
57	Hand Saver Strap	1
58	Circuit Breaker	3
59	Circuit Breaker Connection	2
60	Wireless Remote	2
61	Nut M10	4
62	Flat Washer $\phi 10$	4
63	Spring Washer $\phi 10$	4
64	Screw M10*30	4